

7808 Hermosillo



**BUILDING AND STANDARDS BOARD AGENDA ITEM #5 FOR
WEDNESDAY, JANUARY 28, 2015**

BUILDING SAFETY DIVISION

MEMORANDUM

January 12, 2015

TO: The Honorable Chairman and Board Members

THROUGH: Victor Morrison Vega, Deputy Director, Planning & Inspections Department

FROM: Ron Roth, C.B.O., Chief Building Inspector CBO

SUBJECT: 7808 Hermosillo Dr., El Paso, Texas, 79915

The following is a brief chronology of the investigation of the referenced location:

- 1) First investigated on November 6, 2014. The single family dwelling was built on or about 1952, constructed of CMU walls and wood framed roof structure. The structure was found open, abandoned, in a state of disrepair and accessible to unwanted persons. The structure sustained extensive fire damage on June 2014. The exterior of the structure is showing signs of rapid deterioration due to lack of maintenance. The roof and ceiling system wood members are exposed and decaying. The property is full of weeds, trash and debris.
- 2) Certified notices of the public hearing scheduled for January 28, 2015, were mailed to the owners and all interested parties on January 8, 2015.
- 3) As of January 12, 2015, \$1089.59 is owed in taxes.

The owners have been notified of the property maintenance violations at this property. To date there has been no response or corrective action taken and therefore the Division recommends that it be found:

- 1) That the structure is substandard, and unfit for habitation or use and a hazard to the public health, safety, and welfare.
- 2) That structure is not in substantial compliance with the municipal ordinances regulating fire protection, structural integrity, and disposal of refuse; and
- 3) That structure's certificate of occupancy be revoked; and
- 4) That the structure can be rehabilitated ; and
- 5) That the structure be secured within thirty (30) days and maintained secure thereafter; and
- 6) That the premises be cleaned and maintained clean of all weeds, trash, and debris within thirty (30) days, and maintained clean thereafter and
- 7) That upon failure by the owner or any other interested party to comply with the order of the Building and Standards Commission the City may take whatever action is necessary to bring the property into compliance, and place a lien on the property for the work which will be done by the City.

Building Safety Division
11-7-2014
NOTICE OF VIOLATION

David Torres & Elvira M
7808 Hermosillo Dr.
El Paso, Texas 79915-2702

Re: 7808 Hermosillo
Blk: 3 Hervey Place
Lot: 21
Zoned:R-3
ENHS14-02217
91-7199-9991-7030-7770-0780

To All Owners, Lienholders, and Mortgagees:

An inspection at the above referenced address has revealed that the structure is in violation of the El Paso Municipal Code, Chapter 18.50, Property Maintenance Code, which states:

18.50.108.1 General.

When a structure or equipment is found by the Director to be unsafe, or when a structure is found unfit for human occupancy, or is found unlawful, such structure or equipment shall be condemned pursuant to the provisions of Title 2.38 of the Municipal Code.

The El Paso Municipal Code Chapter 18.50 International Property Maintenance Code defines unsafe structure as follows:

18.50.108.1.1 Unsafe Structures.

An unsafe structure is one that is found to be dangerous to the life, health, property or safety of the public or the occupants of the structure by not providing minimum safeguards to protect or warn occupants in the event of fire, or because such structure contains unsafe equipment or is so damaged, decayed, dilapidated, structurally unsafe or of such faulty construction or unstable foundation, that partial or complete collapse is possible.

18.50.108.1.2 Unsafe Equipment

Unsafe equipment includes any boiler, heating equipment, elevator, moving stairway, electrical wiring or device, flammable liquid containers, or other equipment on the premises or within the structure that is in such disrepair or

condition that such equipment is a hazard to life, health, property or safety of the public or occupants of the premises or structure.

18.50.108.1.3 Structure Unfit for Human Occupancy.

A structure is unfit for human occupancy whenever the Director finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is unsanitary, vermin or rat infested, contains filth or contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public

The structure located at **7808 Hermosillo Dr.** is in violation of the requirements found in the following sections of the 2009 International Property Maintenance Code as adopted in the El Paso City Code, Chapter 18.50, Property Maintenance Code:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]
- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]
- c. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 305.1, 305.2, 305.3, 305.4, 305.5, 305.6]
- d. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- e. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- f. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]

- g. The building must comply with the minimum criteria and conditions for light. [Sec.402.1, 402.2, 402.3]
- h. The building must comply with the minimum criteria and conditions for ventilation. [Sec.403.1, 403.2, 403.3, 403.4, 403.5]
- i. The requirement for Privacy, minimum room dimensions, prohibited occupancy or food preparation spaces not met. [Sec.404.1, 404.2, 404.3, 404.4, 404.5, 404.6, 404.7]
- j. The building must comply with the minimum criteria of the provisions for required facilities. [Sec. 502.1, 502.2, 502.3, 502.4,502.4.1, 502.5]
- k. The building must comply with the minimum criteria of the provisions for toilet rooms. [Sec. 503.1, 503.2, 503.3, 503.4]
- l. The building must comply with the minimum criteria of the provisions for plumbing systems and fixtures. [Sec. 504.1, 504.2, 504.3]
- m. The building must comply with the minimum criteria of the provisions for water systems. [Sec. 505.1, 505.2, 505.3, 505.4]
- n. The building must comply with the minimum criteria of the provisions for sanitary drainage systems. [Sec.506.1, 506.2, 506.3]
- o. The drainage of roofs and paved areas, yards and courts, and other open areas on the premises shall not be discharged in a manner that creates a public nuisance. [Sec. 507.1]
- p. The building must comply with the minimum criteria of the provisions for heating facilities. [Sec. 602.2, 602.3, 602.4, 602.5]
- q. All mechanical equipment and fireplaces shall be properly installed and maintained. [Sec.603.1, 603.2, 603.3, 603.4, 603.5, 603.6]
- r. The building must comply with the minimum criteria of the provisions for electrical facilities. [Sec. 604.1,604.2, 604.3, 604.3.1, 604.3.1.1, 604.3.2, 604.3.2.1]
- s. All electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner. [Sec. 605.1, 605.2, 605.3]
- t. Duct systems shall be maintained free of obstructions and shall be capable of performing the required function. [Sec. 607.1]

- u. Means of egress & Emergency escape opening - A safe, continuous and unobstructed path of travel has not been provided from all points in the building or structure to the public way. [Sec. 702.1, 702.2, 702.3, 702.4]
- v. The required fire-resistance rating of fire-resistance-rated walls, fire stops, shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2]
- w. All systems, devices and equipment to detect a fire, actuate an alarm, or suppress or control a fire or any combination thereof shall be maintained in an operable condition at all times. [Sec. 704.1, 704.1.1, 704.2, 704.3, 704.4]
- x. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]
- y. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within 30 days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the City Development Department, Building Safety Division.

As a result of the aforementioned violations, the following action may be taken:

- a. This case is being submitted to the City Building and Standards Commission for unsafe structures proceedings. The Building and Standards Commission will decide if the structure is unsafe and if it should be vacated and secured, or demolished as per Title 2.38 of the El Paso Municipal Code.
- b. By authority of Chapter 18.02.108.10 of the El Paso Municipal Code the electrical service at this property may be disconnected at the request of the City Development Department, Building Safety Division because of Electrical Code violations.

Many of these corrections will require a permit. Permits for commercial or rental property must be taken out by a bonded and insured contractor who is registered with the City of El Paso.

According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Building Safety Division office, 801 Texas Ave., El Paso, Texas,

79901, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Should you have any questions regarding this matter, please contact me at (915) 478-0352.

Salvador Reyes
Building Inspector

NOTICE OF PUBLIC HEARING

To all interested parties:

The owners, mortgagee, lien holders and any others with a legal interest in the property described below are hereby ordered to appear before the Building and Standards Commission, herein after referred to as the “Commission”, at the following time and place:

LOCATION: El Paso City Hall, City Council Chamber, 300 N. Campbell, 1st Floor, El Paso, Texas 79901

DATE: January 28, 2015

TIME: 5:30 p.m.

PROPERTY: 7808 Hermosillo Dr. 79915, El Paso, Texas 79915 also described as Lot 21, Block 3, FIRST PREPLAT OF HERVEY PLACE, an addition to the City of El Paso, El Paso County, Texas, according to the Plat thereof recorded in Volume 3, Page 39, Real Property Records of El Paso County, Texas.

The property has been determined to be substandard based upon violations of the minimum standards of the 2009 Building Codes, adopted and incorporated in the El Paso City Code, Chapter 18, more specifically addressed below.

According to the real property records of El Paso County, and other relevant public records, David and Elvira M. Torres, 7808 Hermosillo Dr., El Paso, Texas, 79915-2702, are the owners, herein after referred to as the “Owners” of the property. If you no longer own or have an interest in the property, you must execute an affidavit stating that you no longer own or have an interest in the property and stating the name and last known address of the person who acquired the property from you, if applicable. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Building and Safety Division of the Planning and Inspections Department, 801 Texas, El Paso, Texas 79901, no later than the 20th day after the date you receive this notice. If you do not execute and deliver the affidavit, it will be presumed that you own or have an interest in the property, even if you do not.

On or about November 6, 2014, an inspection of the property was conducted by the Building Safety Division and the following violations were identified:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]

- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]
- c. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 305.1, 305.2, 305.3, 305.4, 305.5, 305.6]
- d. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- e. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- f. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
- g. The building must comply with the minimum criteria and conditions for light. [Sec.402.1, 402.2, 402.3]
- h. The building must comply with the minimum criteria and conditions for ventilation. [Sec.403.1, 403.2, 403.3, 403.4, 403.5]
- i. The requirement for Privacy, minimum room dimensions, prohibited occupancy or food preparation spaces not met. [Sec.404.1, 404.2, 404.3, 404.4, 404.5, 404.6, 404.7]
- j. The building must comply with the minimum criteria of the provisions for required facilities. [Sec. 502.1, 502.2, 502.3, 502.4,502.4.1, 502.5]
- k. The building must comply with the minimum criteria of the provisions for toilet rooms. [Sec. 503.1, 503.2, 503.3, 503.4]
- l. The building must comply with the minimum criteria of the provisions for plumbing systems and fixtures. [Sec. 504.1, 504.2, 504.3]
- m. The building must comply with the minimum criteria of the provisions for water systems. [Sec. 505.1, 505.2, 505.3, 505.4]
- n. The building must comply with the minimum criteria of the provisions for sanitary drainage systems. [Sec.506.1, 506.2, 506.3]

- o. The building must comply with the minimum criteria of the provisions for heating facilities. [Sec. 602.2, 602.3, 602.4, 602.5]
- p. All mechanical equipment and fireplaces shall be properly installed and maintained. [Sec.603.1, 603.2, 603.3, 603.4, 603.5, 603.6]
- q. The building must comply with the minimum criteria of the provisions for electrical facilities. [Sec. 604.1,604.2, 604.3, 604.3.1, 604.3.1.1, 604.3.2, 604.3.2.1]
- r. All electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner. [Sec. 605.1, 605.2, 605.3]
- s. Duct systems shall be maintained free of obstructions and shall be capable of performing the required function. [Sec. 607.1]
- t. Means of egress & Emergency escape opening - A safe, continuous and unobstructed path of travel has not been provided from all points in the building or structure to the public way. [Sec. 702.1, 702.2, 702.3, 702.4]
- u. All systems, devices and equipment to detect a fire, actuate an alarm, or suppress or control a fire or any combination thereof shall be maintained in an operable condition at all times. [Sec. 704.1, 704.1.1, 704.2, 704.3, 704.4]
- v. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]
- w. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within 30 days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the City Development Department, Building Safety Division.

The owners are entitled to show cause that the property is safe, does not constitute a dangerous structure and should not be declared a nuisance and ordered abated by presenting relevant evidence and testimony. If the owners advocates for repair, then they bear the burden of proof to demonstrate the scope of any work that may be required to bring the property into compliance with Chapter 18.50 and the time it will take to reasonably perform the work. The allowable time periods for repair are governed by Texas Local Government Code, Sections 214.001(h), (i), (j) and (k). Any document relied upon to demonstrate that the property is safe or that it can be repaired must be presented to the Commission at the hearing, including building plans, specifications, drawings, or reports from professionals and any other relevant documentation.

If the owners fail to comply with the order of the Commission, the City may pursue one or more of the following actions:

Perform any and all work necessary to bring the property into compliance with the Commission's order;

Assess civil penalties, provided for in the Commission's order, in an amount not to exceed \$1,000 per day or \$10 per day if the Property has a homestead exemption, that will accrue interest of 10% per year until paid in full;

Appoint a receiver as permitted by state law; and

Any other remedies permitted by state law.

Commission orders may be appealed to the State District Court within 30 days of the Final order.

The Commission's authority and procedures in regard to a Dangerous Structure Hearing may be found in Chapter 2.38 of the El Paso City Code and in their duly adopted bylaws. A copy of the ordinance adopting the most current version of Chapter 2.38 is enclosed. The bylaws may be obtained at the Building Safety Division of the Planning and Inspections Department, 801 Texas, El Paso, Texas 79901 or by calling (915) 212-1815.

This notice will be recorded in the real property records of El Paso County and will be binding on subsequent grantees, lien holders or other transferees of an interest in the Property.

The City Clerk is ordered to provide notice of this hearing to the record owners and all other interested parties, required by law, who are listed following this notice, and file this notice in the real property records of El Paso County.

FAILURE OF THE OWNER AND/OR LIENHOLDER OR MORTGAGEE TO TAKE THE ORDERED ACTION MAY RESULT IN THE CITY TAKING THE ORDERED ACTION AND FILING A LIEN AGAINST THE PROPERTY.

The City of El Paso appreciates your cooperation and prompt attention to remedying the nuisances on the property. Please do not hesitate to contact me should you have any additional questions, comments or concerns relative to this notice.

APPROVED AS TO FORM

APPROVED AS TO CONTENT

Wendi N Vineyard
Assistant City Attorney

Ron Roth, C.B.O.
Deputy Building Official

I, RICHARDA DUFFY MOMSEN, City Clerk of the City of El Paso, hereby certify that a true and correct copy of the foregoing Notice regarding the property located at **7808 Hermosillo Dr., El Paso, Texas 79915** was PUBLISHED in the official City newspaper on the ___ day of _____, 2015.

Richarda Duffy Momsen

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas 79915** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

David and Elvira M. Torres
7807 Hermosillo
El Paso, Texas 79915

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas 79915** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

David R. Torres
2575 Apodaca Road
Las Cruces, New Mexico 88005

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas 79915** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

David Torres
9878 Isaac Dr.
El Paso, Texas 79927

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas 79915** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

David Torres
10535 Montwood Dr. Apt. 130
El Paso, Texas 79935-2722

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas 79915** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

David Torres
8428 Villanova Dr.
El Paso, Texas 79907-7507

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas 79915** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

David R. Torres
P. O. Box 371042
El Paso, Texas 79937-1042

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas 79915** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

David Torres
3401 Bisbee Ave.
El Paso, Texas 79930

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas 79915** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Midland Funding LLC
8875 Aero Drive
San Diego, CA 92123

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas 79915** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

City Financial Servicing LLC
300 St. Paul Place
Baltimore, Maryland 21202

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas 79915** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Citi Financial Inc.
9100 Viscount, Suite I
El Paso, Texas 79925

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas 79915** was HAND-DELIVERED to:

City of El Paso
C/O City Clerk
300 N. Campbell
El Paso, Texas 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas, 79915** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Governor of the Ysleta Del Sur Pueblo Indian Tribe
AKA Tigua Indian Community
119 S. Old Pueblo Road
El Paso, Texas 79907

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas 79915**, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso Central Appraisal District
5801 Trowbridge Ave.
El Paso, Texas 79925

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas 79915**, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso County Probate Court
500 E. San Antonio Avenue, Suite 105
El Paso, Texas 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at **7808 Hermosillo Dr., El Paso, Texas 79915**, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Delgado, Acosta, Spencer
Linebarger, Heard & Perez, LLP
Attn: Bonnie Cooper
221 N. Kansas Suite 1400
El Paso, Texas 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice was POSTED at **7808 Hermosillo Dr., El Paso, Texas, 79915.**

Date: _____

Time: _____

Inspector: _____



UNSAFE STRUCTURES REPORT

PLANNING & INSPECTIONS DEPARTMENT

DATE OF EXAMINATION: January 8, 2015

REP. DISTRICT: 7

ADDRESS: 7808 Hermosillo Dr.

ZONED: R-3

LEGAL DESCRIPTION: Lot 21, Block 3, FIRST PREPLAT OF HERVEY PLACE, an addition to the City of El Paso, El Paso County, Texas, according to the Plat thereof recorded in Volume 3, Page 39, Real Property Records of El Paso County, Texas.

OWNER: David Torres

ADDRESS: 7808 Hermosillo Dr.
El Paso Tx, 79915

BUILDING USE: Residential

TYPE OF CONSTRUCTION: Type V.

CONDITION: Unable to determine condition due to fire damage. A structural engineer should be hired to evaluate actual condition.

FOUNDATION WALL: N/A

CONDITION: N/A

FLOOR STRUCTURE: Concrete slab

CONDITION: Unable to determine. A structural engineer should be hired to evaluate actual condition.

EXTERIOR WALLS: Cinder Block

HEIGHT: 12' +/-

THICKNESS: 10" +/-

CONDITION: Poor, due to weather and fire damage, Exterior walls will require a structural engineer to evaluate the entire system for structural stability and submit a report to this department with all corrective actions required to bring the system up to minimum code

INTERIOR WALLS & CEILINGS: Walls are wood framed covered with Gypsum board or wood. Ceilings are wood frame system covered with gypsum board and or wood.

CONDITION: Poor, due to fire and smoke damage, lack of maintenance and exposure to the elements, the structures are showing structural failure and are in advance state of disrepair. There are holes in the walls throughout the property. A structural engineer will need to evaluate the entire

wall system for structural stability and submit a report to this department with all corrective actions required to bring the system up to minimum code.

ROOF STRUCTURE: Wood framing system covered in both rolled asphalt and 3 tab shingles.

CONDITION: Poor. The roof system is deteriorated due to fire damage and lack of maintenance and exposure to the elements. The elements are dry rotten. A licensed roofing contractor in the state of Texas should be hired to evaluate the roofing system.

DOORS, WINDOWS, ETC.: Metal frame windows, Wood doors.

CONDITION: Poor, Several windows and doors are broken, damaged or missing due to exposure to the weather and fire.

MEANS OF EGRESS: Does not meet code

CONDITION: Poor. The windows are not in compliance with the minimum code requirements. The doors are not operable.

PLUMBING: Poor. A licensed plumbing contractor must be hired to evaluate the entire plumbing system and submit a report to this department with the corrective action required to bring the system up to minimum code compliance.

ELECTRICAL: Poor. A licensed electrical contractor must be hired to evaluate the entire electrical system and submit a report to this department with the corrective action required to bring the system up to minimum code compliance.

MECHANICAL: Poor. A licensed mechanical contractor must be hired to evaluate the entire mechanical system and submit a report to this department with the corrective action required to bring the system up to minimum code compliance.

IF CONDEMNED, HOW MANY PERSONS WILL BE AFFECTED: 0

WARNING POSTED: Yes **BARRICADED:** No **POLICE AID REQD.:** No

REMARKS: Structure has extensive fire damage to living room, kitchen, restroom and bedrooms; the rest of the home has smoke damage. The roofing system has failed over the restroom day light comes through. The department recommends that the structure can be rehabilitated. That the structure be secured within thirty (30) days and maintained secure thereafter. That the premises be cleaned within thirty (30) days and maintained clean thereafter.

Salvador Reyes
Building Inspector

TAX REPORT

Appraisal & Collection Technologies - EL PASO

Action Edit Query Record Field Help Entitlements Accounts Statements Window

ORACLE

Account Status

Prev. Acc... Next Acc... Prev. Owner Next Owner Acct History Acct Summary **Notes** Documents Go To:

EVAR 01/12/2015 08:01
ACT8006 v1.264 ACTEP

STATUS DETAIL Expand Fees Summary

Account Information

Account No. H333-999-0030-8100 Roll Code REAL PROPERTY

Certified Owner TORRES DAVID & ELVIRA M

Parcel Address 7808 HERMOSILLO DR

Amount Due as of 01/12/2015 CAD No. 10024

Tax Units

Tax Unit Description

List of Tax Units

1 5 6 7 8 61

AG INCLUDED Remove Fees Countywide

Tax Unit, Yr, Rec. Type

Tax Unit Year Rec. Type Multi Select

Amount Due/Paid Information

Year	Gross Value	H	O	V	D	Excodes	Base Levy	Paid Levy	Write-Off	Remaining Levy	Fees	Refund	Amount Due
2014	\$80,332	Y	Y			Excodes	\$1,089.59	\$0.00	\$0.00	\$1,089.59	\$0.00	\$0.00	\$1,089.59
2013	\$80,332	Y	Y			Excodes	\$1,061.36	\$1,061.36	\$0.00	\$0.00	\$37.20	\$0.00	\$0.00
2012	\$80,332	Y	Y			Excodes	\$1,013.97	\$1,013.97	\$0.00	\$0.00	\$121.68	\$0.00	\$0.00
2011	\$82,944	Y	Y			Excodes	\$1,023.21	\$1,023.21	\$0.00	\$0.00	\$204.64	\$0.00	\$0.00
2010	\$82,944	Y	Y			Excodes	\$1,007.82	\$1,007.82	\$0.00	\$0.00	\$282.19	\$0.00	\$0.00
2009	\$83,929	Y	Y			Excodes	\$992.23	\$992.23	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2008	\$83,458	Y	Y			Excodes	\$991.37	\$991.37	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2007	\$83,458	Y	Y			Excodes	\$942.09	\$942.09	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2006	\$82,261	Y	Y			Excodes	\$990.20	\$990.20	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Totals							\$17,494.05	\$16,404.46	\$0.00	\$1,089.59	\$823.19	\$0.00	\$1,089.59

Last Payment Date

Last Payer **Alert**