

3915 Tularosa



**BUILDING AND STANDARDS BOARD AGENDA ITEM # 3 FOR
WEDNESDAY, JUNE 27, 2012**

CODE COMPLIANCE DIVISION

MEMORANDUM

June 20, 2012

TO: The Honorable Chairman and Board Members

THROUGH: Kurt Fenstermacher, Deputy Director, Environmental Services Department

FROM: Bill Stern, Deputy Building Official

SUBJECT: 3915 Tularosa Avenue, El Paso, Texas, 79903

The following is a brief chronology of the investigation of the referenced location:

- 1) First investigated on April 28, 2010. The single family dwelling was built in 1920, according to Central Appraisal records, constructed of Adobe walls with plaster coating and a wood framed roof structure. The structure was found abandoned and in an advanced state of disrepair. It appears to be used as a commercial storage area. The exterior of the structure is showing signs of rapid deterioration due to lack of maintenance and exposure to the elements. The plaster coating has fallen in several areas exposing the underlying adobe to the elements. There are several structural cracks on the exterior walls that are ready to collapse. The roof and ceiling assembly and roof coverings have not been maintained allowing the natural light to seep through. There is exposed wood framing that is decaying due to exposure to the elements.
- 2) A certified condemnation letter was mailed to Saul O. Granados.
- 3) Certified notices of the public hearing scheduled for June 27, 2012, were mailed to the owners and all interested parties on June 12, 2012.
- 4) As of June 20, 2012, no taxes are owed.

The owners have been notified of the property maintenance violations at this property. To date there has been no corrective action taken, and therefore the Division recommends that it be found:

- 1) That the structure is substandard, and unfit for habitation or use and a hazard to the public health, safety, and welfare; and
- 2) That the structure is not in substantial compliance with the municipal ordinances regulating fire protection, structural integrity, and disposal of refuse; and
- 3) That the structures' certificate of occupancy be revoked; and
- 4) That the structure cannot be rehabilitated; and
- 5) That the structure be demolished within thirty (30) days; and
- 6) That the premises be cleaned and maintained clean of all weeds, trash, and debris within thirty (30) days; and
- 7) That upon failure by the owner or any other interested party to comply with the order of the Building and Standards Commission the City may take whatever action is necessary to bring the property into compliance, and place a lien on the property for the work which will be done by the City.

Code Compliance Division
March 5, 2012

NOTICE OF VIOLATION

Saul O Granados
8228 Loma Terrace Rd.
El Paso, Texas 79907-1535

Re: 3915 Tularosa Ave.
Blk: 21 Government Hill
Lot: 9
Zoned: R-5
ENHS12-00164
7108 2133 3932 6880 8420

To All Owners, Lienholders, and Mortgagees:

An inspection at the above referenced address has revealed that the structure is in violation of the El Paso Municipal Code, Chapter 18.50, Property Maintenance Code, which states:

18.50.108.1 General.

When a structure or equipment is found by the Director to be unsafe, or when a structure is found unfit for human occupancy, or is found unlawful, such structure or equipment shall be condemned pursuant to the provisions of Chapter 2.38 of this code.

The El Paso Municipal Code Chapter 18.50 International Property Maintenance Code defines unsafe structure as follows:

18.50.108.1.1 Unsafe Structures.

An unsafe structure is one that is found to be dangerous to the life, health, property or safety of the public or the occupants of the structure by not providing minimum safeguards to protect or warn occupants in the event of fire, or because such structure contains unsafe equipment or is so damaged, decayed, dilapidated, structurally unsafe or of such faulty construction or unstable foundation, that partial or complete collapse is possible.

18.50.108.1.2 Unsafe Equipment

Unsafe equipment includes any boiler, heating equipment, elevator, moving stairway, electrical wiring or device, flammable liquid containers, or other equipment on the premises or within the structure that is in such disrepair or condition that such equipment is a hazard to life, health, property or safety of the public or occupants of the premises or structure.

18.50.108.1.3 Structure Unfit for Human Occupancy.

A structure is unfit for human occupancy whenever the Director finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is unsanitary, vermin or rat infested, contains filth or

contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public

The structure located at **3915 Tularosa Ave., El Paso, Texas, 79903** is in violation of the requirements found in the following sections of the 2009 International Property Maintenance Code as adopted in the El Paso City Code, Chapter 18.50, Property Maintenance Code:

- a. The floors have not been maintained in a safe manner. [Sec. 304.1.1.9]
- b. The walls have not been maintained in a safe manner free of holes and cracks. [Sec. 304.6 & Sec.305.2]
- c. The roof structure has not been maintained free of defects that may cause leaks. [Sec. 304.7]
- d. The means of egress is/are inadequate and do not meet minimum code requirements. [Sec. 702.4]
- e. The plumbing system is inadequate and does not meet minimum code requirements. [Sec. 504.1]
- f. The electrical system is inadequate and does not meet minimum code requirements. [Sec. 604.3]
- g. The HVAC system is inadequate and does not meet minimum code requirements. [Sec. 603.1]
- h. The structure is open and accessible to unauthorized entry. [Sec. 301.3]
- i. The premises are full of weeds, trash, and debris [Sec. 302.1 & Sec. 302.4].
- j. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]
- k. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within 30 days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the Environmental Services Department, Code Compliance Division.

As a result of the aforementioned violations, the following action may be taken:

- a. This case is being submitted to the City Prosecutor's Office for court proceedings. The court will decide if the structure is unsafe and if it should be vacated and secured, or demolished as per Chapter 2.38 of the El Paso Municipal Code.
- b. By authority of Chapter 18.02.103.10.3.3 of the El Paso Municipal Code the electrical service at this property may be disconnected at the request of the Environmental Services Department, Code Compliance Division because of Electrical Code violations.

Many of these corrections will require a permit. Permits for commercial or rental property must be taken out by a bonded and insured contractor who is registered with the City of El Paso.

According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Code Compliance Division office, 7969 San Paulo Dr., El Paso, Texas, 79907, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Should you have any questions regarding this matter, please contact me at 599-6290.

Nellie Avalos
Building Inspector

NOTICE OF PUBLIC HEARING

To all interested parties:

The owners, mortgagee, lien holders and any others with a legal interest in the property described below are hereby ordered to appear before the Building and Standards Commission, herein after referred to as the "Commission", at the following time and place:

LOCATION: El Paso City Hall, 2 Civic Center Plaza, Council Chamber, 2nd Floor El Paso, Texas 79901

DATE: June 27, 2012

TIME: 5:30 p.m.

PROPERTY: 3915 Tularosa Avenue, Lot 9, Block 21 of Government Hill

The Property has been determined to be substandard based upon violations of the minimum standards of the 2009 Building Codes, adopted and incorporated in the El Paso City Code, Chapter 18.50 Property Maintenance Code, more specifically addressed below.

According to the real property records of El Paso County, and other relevant public records, Saul Granados, 8228 Loma Terrace Road, El Paso, Texas, 79907, is the owner, herein after referred to as the "Owner" of the Property. If you no longer own or have an interest in the Property, you must execute an affidavit stating that you no longer own or have an interest in the Property and stating the name and last known address of the person who acquired the property from you, if applicable. The affidavit must be delivered in person or by certified mail, return receipt requested, to Building Standards Enforcement Division, 7969 San Paulo Drive, El Paso, Texas 79907, no later than the 20th day after the date you receive this notice. If you do not execute and deliver the affidavit, it will be presumed that you own or have an interest in the Property, even if you do not.

On or about March 5, 2012 an inspection of the Property was conducted by the Environmental Services Division and the following violations were identified:

- a. The floors have not been maintained in a safe manner. (Code Sec. 304.1.1.9 of the 2009 International Property Maintenance Code (IPMC))
- b. The walls have not been maintained in a safe manner free of holes and cracks. (Sec. 304.6 & Sec.305.2 of the 2009 IPMC)
- c. The roof structure has not been maintained free of defects that may cause leaks. (Sec. 304.7 of the 2009 IPMC)
- d. The means of egress is/are inadequate and do not meet minimum code requirements. (Sec. 702.4 of the 2009 IPMC)
- e. The plumbing system is inadequate and does not meet minimum code requirements. (Sec. 504.1 of the 2009 IPMC)

- f. The electrical system is inadequate and does not meet minimum code requirements. (Sec. 604.3 of the 2009 IPMC)
- g. The HVAC system is inadequate and does not meet minimum code requirements. (Sec. 603.1 of the 2009 IPMC)
- h. The structure is open and accessible to unauthorized entry. (Sec. 301.3 of the 2009 IPMC)
- i. The premises are full of weeds, trash, and debris (Sec. 302.1 & Sec. 302.4 of the 2009 IPMC)
- j. The structure needs to be secured from unwanted entry and ongoing vandalism. (Sec. 108.2 of the 2009 IPMC)

The Owner is entitled to show cause that the Property is safe, does not constitute a Dangerous Structure and should not be declared a nuisance and ordered abated by presenting relevant evidence and testimony. If the Owner advocates for repair, then he bears the burden of proof to demonstrate the scope of any work that may be required to bring the property into compliance with Chapter 18.50 and the time it will take to reasonably perform the work. The allowable time periods for repair are governed by Texas Local Government Code, Sections 214.001(h), (i), (j) and (k). Any document relied upon to demonstrate that the Property is safe or that it can be repaired must be presented to the Commission at the hearing, including building plans, specifications, drawings, or reports from professionals and any other relevant documentation.

If the Owner fails to comply with the order of the Commission the City may pursue one or more of the following actions:

Perform any and all work necessary to bring the property into compliance with the Commission's order;

Assess civil penalties, provided for in the Commission's order, in an amount not to exceed \$1,000 per day or \$10 per day if the Property has a homestead exemption, that will accrue interest of 10% per year until paid in full;

Appoint a receiver as permitted by state law; and

Any other remedies permitted by state law.

Commission orders may be appealed to the State District Court within 30 days of the Final order.

The Commission's authority and procedures in regard to a Dangerous Structure Hearing may be found in Chapter 2.38 of the El Paso City Code and in their duly adopted bylaws. A copy of the ordinance adopting the most current version of Chapter 2.38 is enclosed. The bylaws may be obtained at the Building Standards Enforcement Division, 7969 San Paulo Drive, El Paso, Texas 79907 or by calling (915) 599-6290.

This notice will be recorded in the real property records of El Paso County and will be binding on subsequent grantees, lien holders or other transferees of an interest in the Property.

The City Clerk is ordered to provide notice of this hearing to the record owners and all other interested parties, required by law, who are listed following this notice, and file this notice in the real property records of El Paso County.

FAILURE OF THE OWNER AND/OR LIENHOLDER OR MORTGAGEE TO TAKE THE ORDERED ACTION MAY RESULT IN THE CITY TAKING THE ORDERED ACTION AND FILING A LIEN AGAINST THE PROPERTY.

The City of El Paso appreciates your cooperation and prompt attention to remedying the nuisances on the Property. Please do not hesitate to contact me should you have any additional questions, comments or concerns relative to this notice.

APPROVED AS TO FORM
CONTENT

APPROVED AS TO

Lesley J. Nicholes
Assistant City Attorney

Bill Stern, C.B.O.
Deputy Building Official
Code Compliance Division

I, RICHARDA DUFFY MOMSEN, City Clerk of the City of El Paso, hereby certify that a true and correct copy of the foregoing Notice regarding the property located at 3915 Tularosa Avenue, El Paso, Texas was PUBLISHED in the official City newspaper on the ____ day of _____, 2012.

Richarda Duffy Momsen

I certify that a true and correct copy of the foregoing Notice regarding the property at 3915 Tularosa Avenue was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Saul O. Granados
8228 Loma Terrace Road
El Paso, Texas 79907

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 3915 Tularosa Avenue was HAND-DELIVERED to:

City of El Paso
C/O City Clerk
#2 Civic Center Plaza
El Paso, TX 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 3915 Tularosa Avenue was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Governor of the Ysleta Del Sur Pueblo Indian Tribe
AKA Tigua Indian Community
119 S. Old Pueblo Road
El Paso, Texas 79907

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 3915 Tularosa Avenue was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso Central Appraisal District
5801 Trowbridge Ave.
El Paso, Texas 79925

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 3915 Tularosa Avenue was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso County Probate Court
500 E. San Antonio Avenue, Suite 703
El Paso, Texas 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 3915 Tularosa Avenue was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Delgado, Acosta, Spencer
Linebarger, Heard & Perez, LLP
Attn: Bonnie Cooper
221 N. Kansas Suite 1400
El Paso, TX 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice was POSTED at 3915 Tularosa Avenue El Paso, Texas.

Date: _____
Time: _____
Inspector: _____



UNSAFE STRUCTURES REPORT

BUILDING PERMITS AND INSPECTIONS

DATE OF EXAMINATION: June 12, 2012

REP. DISTRICT: 8

ADDRESS: 3915 Tularosa Avenue

ZONED: R-5

LEGAL DESCRIPTION: Lot 9, Block 21, GOVERNMENT HILL, addition to the City of El Paso, Texas.

OWNER: Saul O. Granados

ADDRESS: 3915 Tularosa Avenue
El Paso, Texas 79903

BUILDING USE: Abandoned single family dwelling

TYPE OF CONSTRUCTION: V, Adobe walls w/wood frame and plaster coating covering

FOOTINGS: Concrete

CONDITION: Unable to determine condition of footing due to subterranean placement. A structural engineer should be hired to evaluate actual condition.

FOUNDATION WALL: Concrete stem wall

CONDITION: Poor. Deterioration noted due to lack of maintenance.

FLOOR STRUCTURE: Hardwood flooring system.

CONDITION: Poor. Hardwood flooring is exposed and decaying. A structural engineer or registered contractor must be hired to evaluate the flooring system.

EXTERIOR WALLS: Wood frame Adobe walls with plaster covering

HEIGHT: 12' +/- **THICKNESS:** 10" - 12"

CONDITION: Poor. Several structural deficiencies found, exposed underlying Adobe is crumbling. A structural engineer should be hired to evaluate structural elements of the building and submit a report on the corrections required to make the building safe.

INTERIOR WALLS & CEILINGS: Wood frame, adobe w/plaster covering.

CONDITION: Poor. Several structural deficiencies found, exposed underlying Adobe is crumbling. A structural engineer should be hired to evaluate structural elements of the building and submit a report of the required corrections to make the buildings safe

ROOF STRUCTURE: Wood frame w/rolled roofing composition.

CONDITION: Poor. Natural exterior light seeping through exposed roof joists are deteriorated and decaying due to lack of maintenance and exposure to the elements. A licensed roofing contractor in the state of Texas must be hired to evaluate the roofing system and submit a report of required corrections to bring the roof system into code compliance.

DOORS, WINDOWS, ETC.: Wood frame doors/windows.

CONDITION: Poor. The wood frame doors and windows deteriorated. Will need to replace doors and windows, so they are operational and meet egress requirements.

MEANS OF EGRESS: Does not meet code requirements.

CONDITION: Poor. Windows and doors must be replaced to make them operational.

PLUMBING: A licensed plumber should be hired to install a compliant plumbing system.

ELECTRICAL: A licensed electrician should be hired to bring system up to code.

MECHANICAL: A licensed mechanical contractor should be hired to install a compliant mechanical system.

IF CONDEMNED, HOW MANY PERSONS WILL BE AFFECTED: None

WARNING POSTED: Yes

BARRICADED: No

POLICE AID REQD.: No

REMARKS: This abandoned single family residence was built in 1920. The structure was found in a state of disrepair and being used as storage for Hensal Glass Company. The department recommends that the structure be demolished and the property cleaned of all weeds, trash and debris within thirty (30) days..

Nellie Avalos

Building Inspector