

10537 BRISBANE WAY



**BUILDING AND STANDARDS BOARD AGENDA ITEM #5 FOR
WEDNESDAY, AUGUST 26, 2015**

**PLANNING & INSPECTIONS DEPARTMENT
BUILDING SAFETY DIVISION**

MEMORANDUM
AUGUST 14, 2014

TO: The Honorable Chairman and Board Members

THROUGH: Victor Morrison-Vega, Deputy Director, Planning & Inspections Department

FROM: Ron Roth, C.B.O., Deputy Building Official

SUBJECT: 10537 Brisbane Way, El Paso, TX 79924

The following is a brief chronology of the investigation of the referenced location:

- 1) First investigated on or about January 26, April 29, and August 19, 2015. The single family home was built on or about 1967, constructed of wood with brick veneer and a wood framed roof structure. The structure was complained about by the last know tenant to have multiple roof leaks throughout the home. Contact was made with original homeowner and violation letter sent. After communication failed on behalf of the home owner, Inspector went back to follow up and the structure was found open and with a severe case of mold throughout the structure's ceilings and walls.
- 2) A certified condemnation letter was mailed to the owner Wells Fargo Bank NA
- 3) Certified notices of the public hearing scheduled for August 26, 2015 were mailed to the owner and all interested parties on August 05, 2015.
- 4) As of August 13, 2015, \$0.00 is owed in taxes.

The owner has been notified of the property violations at this property. To date there has been little or no response or corrective action taken, and therefore the Department recommends that it be found:

- 1) That the structures are substandard and unfit for habitation or use and a hazard to the public health, safety, and welfare; and
- 2) That the structures are not in substantial compliance with the municipal ordinances regulating structural or service systems integrity, fire protection and disposal of refuse; and
- 3) That the structure's Certificate of Occupancy be revoked; and
- 4) That the structures can be rehabilitated; and
- 5) That the structures be secured within thirty (30) days and remain secure thereafter; and
- 6) That the premises be cleaned of all weeds, trash, and debris within thirty (30) days and maintained clean thereafter; and
- 7) That upon failure by the owners or any other interested party to comply with the order of the Building and Standards Commission, the City may take whatever action is necessary to bring the property into compliance, and place a lien on the property for the work which will be done by the City.

Code Compliance Division
October 14, 2013
NOTICE OF VIOLATION

RODRIGUEZ PABLO & ALMA D
10537 BRISBANE WAY
EL PASO, TX 79924-1932

Re: 10537 BRISBANE WAY
Blk: 103 SUN VALLEY
Lot: 11
Zoned: R-3
ENHS13-00927
9171999991703077561626

To All Owners, Lienholders, and Mortgagees:

An inspection at the above referenced address has revealed that the structure is in violation of the El Paso Municipal Code, Chapter 18.50, Property Maintenance Code, which states:

18.50.108.1 General.

When a structure or equipment is found by the Director to be unsafe, or when a structure is found unfit for human occupancy, or is found unlawful, such structure or equipment shall be condemned pursuant to the provisions of Title 2.38 of the Municipal Code.

The El Paso Municipal Code Chapter 18.50 International Property Maintenance Code defines unsafe structure as follows:

18.50.108.1.1 Unsafe Structures.

An unsafe structure is one that is found to be dangerous to the life, health, property or safety of the public or the occupants of the structure by not providing minimum safeguards to protect or warn occupants in the event of fire, or because such structure contains unsafe equipment or is so damaged, decayed, dilapidated, structurally unsafe or of such faulty construction or unstable foundation, that partial or complete collapse is possible

18.50.108.1.2 Unsafe Equipment

Unsafe equipment includes any boiler, heating equipment, elevator, moving stairway, electrical wiring or device, flammable liquid containers, or other equipment on the premises or within the structure that is in such disrepair or condition that such equipment is a hazard to life, health, property or safety of the public or occupants of the premises or structure.

18.50.108.1.3 Structure Unfit for Human Occupancy.

A structure is unfit for human occupancy whenever the Director finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is unsanitary, vermin or rat infested, contains filth or contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public

The structure located at **10537 BRISBANE WAY** is in violation of the requirements found in the following sections of the 2009 International Property Maintenance Code as adopted in the El Paso City Code, Chapter 18.50, Property Maintenance Code:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]
- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]
- c. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- d. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- e. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
- f. The drainage of roofs and paved areas, yards and courts, and other open areas on the premises shall not be discharged in a manner that creates a public nuisance. [Sec. 507.1]
- g. The required fire-resistance rating of fire-resistance-rated walls, fire stops, shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2]
- h. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]
- i. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within 30 days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the Environmental Services Department, Code Compliance Division.

As a result of the aforementioned violations, the following action may be taken:

- a. This case is being submitted to the City Building and Standards Commission for unsafe structures proceedings. The Building and Standards Commission will decide if the structure is unsafe and if it should be vacated and secured, or demolished as per Title 2.38 of the El Paso Municipal Code.
- b. By authority of Chapter 18.02.103.10.3.3 of the El Paso Municipal Code the electrical service at this property may be disconnected at the request of the Environmental Services Department, Code Compliance Division because of Electrical Code violations.

Many of these corrections will require a permit. Permits for commercial or rental property must be taken out by a bonded and insured contractor who is registered with the City of El Paso.

According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Code Compliance Division office, 7969 San Paulo Dr., El Paso, Texas, 79907, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Should you have any questions regarding this matter, please contact me at 599-6290.


Alexandro Esparza
Building Inspector



The City of El Paso
 Environmental Services
 7969 San Paulo
 El Paso, TX 79907

Environmental Code Compliance

CERTIFIED MAIL



91 7199 9991 7030 7755 1628



RETURN RECEIPT REQUESTED

PAULO A ALVARO RODRIGUEZ
 10577 BRISPAINE WAY
 EL PASO TX 79924-1972
 ENH507-00927
 RR-40657 BRISPAINE WAY

ALVARO

RECEIVED
 OCT 21 2013
 BY: [Signature]

799241972 9991 7030 7755 1628

RTX# 799 DE 1809 0010/19/13
 RETURN TO SENDER
 ATTEMPTED - NOT KNOWN
 UNABLE TO FORWARD
 DC: 79907174669 *1718-02573-15-87

Code Compliance Division
NOVEMBER 19, 2013
NOTICE OF VIOLATION

RODRIGUEZ PABLO & ALMA D
459 SUMMERTON LN
TURLOCK, CA 95382

Re: 10537 BRISBANE WAY
Blk: 103 SUN VALLEY
Lot: 11
Zoned: R-3
ENHS13-00927
9171999991703080113171

To All Owners, Lienholders, and Mortgagees:

An inspection at the above referenced address has revealed that the structure is in violation of the El Paso Municipal Code, Chapter 18.50, Property Maintenance Code, which states:

18.50.108.1 General.

When a structure or equipment is found by the Director to be unsafe, or when a structure is found unfit for human occupancy, or is found unlawful, such structure or equipment shall be condemned pursuant to the provisions of Title 2.38 of the Municipal Code.

The El Paso Municipal Code Chapter 18.50 International Property Maintenance Code defines unsafe structure as follows:

18.50.108.1.1 Unsafe Structures.

An unsafe structure is one that is found to be dangerous to the life, health, property or safety of the public or the occupants of the structure by not providing minimum safeguards to protect or warn occupants in the event of fire, or because such structure contains unsafe equipment or is so damaged, decayed, dilapidated, structurally unsafe or of such faulty construction or unstable foundation, that partial or complete collapse is possible

18.50.108.1.2 Unsafe Equipment

Unsafe equipment includes any boiler, heating equipment, elevator, moving stairway, electrical wiring or device, flammable liquid containers, or other equipment on the premises or within the structure that is in such disrepair or condition that such equipment is a hazard to life, health, property or safety of the public or occupants of the premises or structure.

18.50.108.1.3 Structure Unfit for Human Occupancy.

A structure is unfit for human occupancy whenever the Director finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is unsanitary, vermin or rat infested, contains filth or contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public

The structure located at 10537 BRISBANE WAY is in violation of the requirements found in the following sections of the 2009 International Property Maintenance Code as adopted in the El Paso City Code, Chapter 18.50, Property Maintenance Code:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]
- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]
- c. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- d. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- e. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
- f. The drainage of roofs and paved areas, yards and courts, and other open areas on the premises shall not be discharged in a manner that creates a public nuisance. [Sec. 507.1]
- g. The required fire-resistance rating of fire-resistance-rated walls, fire stops, shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2]
- h. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]

- i. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within 30 days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the Environmental Services Department, Code Compliance Division.

As a result of the aforementioned violations, the following action may be taken:

- a. This case is being submitted to the City Building and Standards Commission for unsafe structures proceedings. The Building and Standards Commission will decide if the structure is unsafe and if it should be vacated and secured, or demolished as per Title 2.38 of the El Paso Municipal Code.
- b. By authority of Chapter 18.02.103.10.3.3 of the El Paso Municipal Code the electrical service at this property may be disconnected at the request of the Environmental Services Department, Code Compliance Division because of Electrical Code violations.

Many of these corrections will require a permit. Permits for commercial or rental property must be taken out by a bonded and insured contractor who is registered with the City of El Paso.

According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Code Compliance Division office, 7969 San Paulo Dr., El Paso, Texas, 79907, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Should you have any questions regarding this matter, please contact me at (915)599-6290 / (915)240-2273.

Alexandro Esparza
Building Inspector

Building Safety Division
January 27, 2015
NOTICE OF VIOLATION

Wells Fargo Bank NA
1 Home Campus
Des Moines, IA 50328-0001

Re: 10537 Brisbane Way
Blk: 103 Sun Valley
Lot: 11
Zoned: R - 3
Case Number: ENHS13-00927
91 7199 9991 7030 7944 1803

To All Owners, Lienholders, and Mortgagees:

An inspection at the above referenced address has revealed that the structure is in violation of the El Paso Municipal Code, Chapter 18.50, Property Maintenance Code, which states:

18.50.108.1 General.

When a structure or equipment is found by the Director to be unsafe, or when a structure is found unfit for human occupancy, or is found unlawful, such structure or equipment shall be condemned pursuant to the provisions of Title 2.38 of the Municipal Code.

The El Paso Municipal Code Chapter 18.50 International Property Maintenance Code defines unsafe structure as follows:

18.50.108.1.1 Unsafe Structures.

An unsafe structure is one that is found to be dangerous to the life, health, property or safety of the public or the occupants of the structure by not providing minimum safeguards to protect or warn occupants in the event of fire, or because such structure contains unsafe equipment or is so damaged, decayed, dilapidated, structurally unsafe or of such faulty construction or unstable foundation, that partial or complete collapse is possible.

18.50.108.1.2 Unsafe Equipment.

Unsafe equipment includes any boiler, heating equipment, elevator, moving stairway, electrical wiring or device, flammable liquid containers, or other equipment on the premises or within the structure that is in such disrepair or condition that such equipment is a hazard to life, health, property or safety of the public or occupants of the premises or structure.

18.50.108.1.3 Structure Unfit for Human Occupancy.

A structure is unfit for human occupancy whenever the Director finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is unsanitary, vermin or rat infested, contains filth or contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public.

The structure located at **10537 Brisbane Way** is in violation of the requirements found in the following sections of the 2009 International Property Maintenance Code as adopted in the El Paso City Code, Chapter 18.50, Property Maintenance Code:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]
- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]
- c. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 305.1, 305.2, 305.3, 305.4, 305.5, 305.6]
- d. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- e. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- f. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
- g. All mechanical equipment and fireplaces shall be properly installed and maintained. [Sec.603.1, 603.2, 603.3, 603.4, 603.5, 603.6]
- h. All electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner. [Sec. 605.1, 605.2, 605.3]
- i. Duct systems shall be maintained free of obstructions and shall be capable of performing the required function. [Sec. 607.1]
- j. Means of egress & Emergency escape opening - A safe, continuous and unobstructed path of travel has not been provided from all points in the building or structure to the public way. [Sec. 702.1, 702.2, 702.3, 702.4]
- k. The required fire-resistance rating of fire-resistance-rated walls, fire stops, shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2]
- l. All systems, devices and equipment to detect a fire, actuate an alarm, or suppress or control a fire or any combination thereof shall be maintained in an operable condition at all times. [Sec. 704.1, 704.1.1, 704.2, 704.3, 704.4]
- m. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]
- n. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within **30** days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the Planning & Inspections Department, Building Safety Division.

As a result of the aforementioned violations, the following action may be taken:

- a. This case is being submitted to the City Building and Standards Commission for unsafe structures proceedings. The Building and Standards Commission will decide if the structure is unsafe and if it should be vacated and secured, or demolished as per Title 2.38 of the El Paso Municipal Code.
- b. By authority of Chapter 18.02.103.10.3.3 of the El Paso Municipal Code the electrical service at this property may be disconnected at the request of the Planning & Inspections Department, Building Safety Division because of Electrical Code violations.

Many of these corrections will require a permit. Permits for commercial or rental property must be taken out by a bonded and insured contractor who is registered with the City of El Paso.

According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Planning & Inspections Department, Building Safety Division office, 801 Texas Ave., El Paso, Texas, 79901, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Should you have any questions regarding this matter, please contact me at (915) 212-1815 or (915) 240-2273.

Alexandro Esparza
Building Inspector

NOTICE OF PUBLIC HEARING

To all interested parties:

The owners, mortgagee, lien holders and any others with a legal interest in the property described below are hereby ordered to appear before the Building and Standards Commission, herein after referred to as the “Commission”, at the following time and place:

LOCATION: El Paso City Hall, City Council Chamber, 300 N. Campbell, 1st Floor, El Paso, Texas 79901

DATE: August 26, 2015

TIME: 5:30 p.m.

PROPERTY: 10537 Brisbane Way, El Paso, Texas 79924 also described as Lot 11, Block 103, SUN VALLEY ADDITION UNIT TEN, an addition to the City of El Paso, El Paso County, Texas, according to the Plat thereof recorded In Volume 17, Page 61, Plat Records of El Paso County, Texas.

The property has been determined to be substandard based upon violations of the minimum standards of the 2009 Building Codes, adopted and incorporated in the El Paso City Code, Chapter 18, more specifically addressed below.

According to the real property records of El Paso County, and other relevant public records, Wells Fargo Bank NA, 1 Home Campus, Des Moines, IA 50328-0001, is the owner, herein after referred to as the “Owner” of the property. If you no longer own or have an interest in the property, you must execute an affidavit stating that you no longer own or have an interest in the property and stating the name and last known address of the person who acquired the property from you, if applicable. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Building and Safety Division of the Planning and Inspections Department, 801 Texas, El Paso, Texas 79901, no later than the 20th day after the date you receive this notice. If you do not execute and deliver the affidavit, it will be presumed that you own or have an interest in the property, even if you do not.

On or about October 11th 2015, an inspection of the property was conducted by the Building Safety Division and the following violations were identified:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]
- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]

- c. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 305.1, 305.2, 305.3, 305.4, 305.5, 305.6]
- d. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- e. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- f. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
- g. All mechanical equipment and fireplaces shall be properly installed and maintained. [Sec.603.1, 603.2, 603.3, 603.4, 603.5, 603.6]
- h. All electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner. [Sec. 605.1, 605.2, 605.3]
- i. Duct systems shall be maintained free of obstructions and shall be capable of performing the required function. [Sec. 607.1]
- j. Means of egress & Emergency escape opening - A safe, continuous and unobstructed path of travel has not been provided from all points in the building or structure to the public way. [Sec. 702.1, 702.2, 702.3, 702.4]
- k. The required fire-resistance rating of fire-resistance-rated walls, fire stops shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2.]
- l. All systems, devices and equipment to detect a fire, actuate an alarm, or suppress or control a fire or any combination thereof shall be maintained in an operable condition at all times. [Sec. 704.1, 704.1.1, 704.2, 704.3, 704.4]
- m. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]
- n. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within 30 days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the City Development Department, Building Safety Division.

The owners are entitled to show cause that the property is safe, does not constitute a dangerous structure and should not be declared a nuisance and ordered abated by presenting relevant evidence and testimony. If the owner advocates for repair, then they bear the burden of proof to demonstrate the scope of any work that may be required to bring the property into compliance

with Chapter 18.50 and the time it will take to reasonably perform the work. The allowable time periods for repair are governed by Texas Local Government Code, Sections 214.001(h), (i), (j) and (k). Any document relied upon to demonstrate that the property is safe or that it can be repaired must be presented to the Commission at the hearing, including building plans, specifications, drawings, or reports from professionals and any other relevant documentation.

If the owners fail to comply with the order of the Commission, the City may pursue one or more of the following actions:

Perform any and all work necessary to bring the property into compliance with the Commission's order;

Assess civil penalties, provided for in the Commission's order, in an amount not to exceed \$1,000 per day or \$10 per day if the Property has a homestead exemption, that will accrue interest of 10% per year until paid in full;

Appoint a receiver as permitted by state law; and

Any other remedies permitted by state law.

Commission orders may be appealed to the State District Court within 30 days of the Final order.

The Commission's authority and procedures in regard to a Dangerous Structure Hearing may be found in Chapter 2.38 of the El Paso City Code and in their duly adopted bylaws. A copy of the ordinance adopting the most current version of Chapter 2.38 is enclosed. The bylaws may be obtained at the Building Safety Division of the Planning and Inspections Department, 801 Texas, El Paso, Texas 79901 or by calling (915) 212-1815.

This notice will be recorded in the real property records of El Paso County and will be binding on subsequent grantees, lien holders or other transferees of an interest in the Property.

The City Clerk is ordered to provide notice of this hearing to the record owners and all other interested parties, required by law, who are listed following this notice, and file this notice in the real property records of El Paso County.

FAILURE OF THE OWNER AND/OR LIENHOLDER OR MORTGAGEE TO TAKE THE ORDERED ACTION MAY RESULT IN THE CITY TAKING THE ORDERED ACTION AND FILING A LIEN AGAINST THE PROPERTY.

The City of El Paso appreciates your cooperation and prompt attention to remedying the nuisances on the property. Please do not hesitate to contact me should you have any additional questions, comments or concerns relative to this notice.

APPROVED AS TO FORM

APPROVED AS TO CONTENT

Wendi N. Vineyard
Assistant City Attorney

Ron Roth, C.B.O.
Deputy Building Official

I, RICHARDA DUFFY MOMSEN, City Clerk of the City of El Paso, hereby certify that a true and correct copy of the foregoing Notice regarding the property located at 10537 Brisbane Way, El Paso, Texas 79924 was PUBLISHED in the official City newspaper on the _____day of _____, 2015.

Richarda Duffy Momsen

I certify that a true and correct copy of the foregoing Notice regarding the property at 10537 Brisbane Way, El Paso, Texas 79924 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Wells Fargo Bank NA
1 Home Campus
Des Moines, IA 50328-0001

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 10537 Brisbane Way, El Paso, Texas 79924 was HAND-DELIVERED to:

City of El Paso
C/O City Clerk
300 N. Campbell
El Paso, Texas 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 10537 Brisbane Way, El Paso, Texas 79924 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Governor of the Ysleta Del Sur Pueblo Indian Tribe
AKA Tigua Indian Community
119 S. Old Pueblo Road
El Paso, Texas 79907

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 10537 Brisbane Way, El Paso, Texas 79924 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso Central Appraisal District
5801 Trowbridge Ave.
El Paso, Texas 79925

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 10537 Brisbane Way, El Paso, Texas 79924 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso County Probate Court
500 E. San Antonio Avenue, Suite 105
El Paso, Texas 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 10537 Brisbane Way, El Paso, Texas 79924 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Delgado, Acosta, Spencer
Linebarger, Heard & Perez, LLP
Attn: Bonnie Cooper
221 N. Kansas Suite 1400
El Paso, Texas 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice was POSTED at 10537 Brisbane Way, El Paso, Texas 79924.

Date: _____
Time: _____
Inspector: _____



UNSAFE STRUCTURES REPORT

PLANNING & INSPECTIONS DEPARTMENT

DATE OF EXAMINATION: August 14, 2015

REP. DISTRICT: 4

ADDRESS: 10537 Brisbane Way

ZONED: R - 3

LEGAL DESCRIPTION: Lot 11, Block 103, SUN VALLEY ADDITION UNIT TEN, an addition to the City of El Paso, El Paso County, Texas.

OWNER: Wells Fargo NA

ADDRESS: 1 Home Campus
Des Moines, IA 50328-0001

BUILDING USE: Vacant Single-Family Dwelling

TYPE OF CONSTRUCTION: V, wood frame w/brick veneer

FOOTINGS: Concrete

CONDITION: Unable to determine condition of footing due to subterranean placement. A structural engineer should be hired to evaluate actual condition.

FOUNDATION WALL: N/A

CONDITION: N/A

FLOOR STRUCTURE: Concrete and some carpet covering

CONDITION: A structural engineer should be hired to evaluate actual condition.

EXTERIOR WALLS: Brick veneer with wood frame

HEIGHT: 8' - 12' +/-

THICKNESS: 4' - 8' +/-

CONDITION: Fair. A structural engineer should be hired to evaluate the structural elements of the building and submit a report on the corrections required to make the building safe.

INTERIOR WALLS & CEILINGS: Wood framing w / gypsum board covering

CONDITION: Interior walls and ceilings have been vandalized and are water damaged due to exposure to the elements. A structural engineer should be hired to evaluate the structural elements of the building and submit a report on the corrections required to make the building safe.

ROOF STRUCTURE: Wood frame Composite Shingle roof covering.

CONDITION: Poor. The roof is dilapidated and there are parts of it exposed to the elements. A registered roofing contractor licensed in the state of Texas must be hired to evaluate the roofing system and submit a report of required corrections to bring the roof system into code compliance.

DOORS, WINDOWS, ETC.: Wood frame doors and aluminum frame windows.

CONDITION: Poor. Several windows and doors are broken. Will need to replace or repair doors and windows, so they are operational and meet egress requirements.

MEANS OF EGRESS: Does not meet code requirements.

CONDITION: Poor. Windows and doors must be replaced to make them operational.

PLUMBING: Substandard plumbing installation and fixtures. A licensed plumber should be hired to bring system up to code.

ELECTRICAL: Substandard electrical installation and fixtures: A licensed electrician should be hired to bring system up to code.

MECHANICAL: Substandard mechanical installation and equipment. A licensed mechanical contractor should be hired to bring system up to code.

IF CONDEMNED, HOW MANY PERSONS WILL BE AFFECTED: 0

WARNING POSTED: Yes **BARRICADED:** No **POLICE AID REQD.:** No

REMARKS: First investigated on or about October 10, 2013. Recently inspected on January 26, April 29, and August 19, 2015. The single family home was built on or about 1967, constructed of wood with brick veneer and a wood framed roof structure. The structure was complained about by the last know tenant to have multiple roof leaks throughout the home. Contact was made with original homeowner and violation letter sent. After communication failed on behalf of the home owner, Inspector went back to follow up and the structure was found open and with a severe case of mold throughout the structure's ceilings and walls.

Alexandro Esparza
Building Inspector

TAX REPORT

Appraisal & Collection Technologies - EL PASO

Action Edit Query Record Field Help Entitlements Accounts Statements Window

Account Status

Prev. Acc... Next Acc... Prev. Owner Next Owner Acct History Acct Summary **Notes** Documents Go To: []

EVAR
ACT8006 v1.266 08/12/2015 12:54:32
ACTEP

STATUS DETAIL Expand Fees Summary

Account Information

Account No. S816-999-1030-2100 Roll Code REAL PROPERTY

Certified Owner WELLS FARGO BANK NA

Parcel Address 10537 BRISBANE WAY

Amount Due as of 08/12/2015 CAD No. 42203

Tax Units

Tax Unit Description

List of Tax Units 1 3 6 7 8 8005

AG INCLUDED Remove Fees Countywide Multi Select

Tax Unit, Yr, Rec. Type

Tax Unit []
Year []
Rec. Type []

Amount Due/Paid Information

Year	Gross Value	H	O	V	D	Excodes	Base Levy	Paid Levy	Write-Off	Remaining Levy	Fees	Refund	Amount Due
2014	\$78,652	Y					\$1,909.26	\$1,909.26	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2013	\$78,652	Y					\$1,871.18	\$1,871.18	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2012	\$78,652	Y					\$1,813.20	\$1,813.20	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2011	\$78,652	Y					\$1,779.16	\$1,779.16	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2010	\$78,652	Y					\$1,762.87	\$1,762.87	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2009	\$82,856	Y					\$1,830.40	\$1,830.40	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2008	\$85,546	Y					\$1,903.59	\$1,903.59	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2007	\$82,464	Y					\$1,788.00	\$1,788.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2006	\$72,901	Y					\$1,861.82	\$1,861.82	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Totals							\$30,207.81	\$30,207.81	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00

Last Payment Date [] Last Payer [] Alert