182 CORONADO

BUILDING AND STANDARDS BOARD AGENDA ITEM # 4 FOR WEDNESDAY, FEBRUARY 28, 2007

DEVELOPMENT SERVICES
BUILDING PERMITS AND INSPECTIONS

MEMORANDUM

February 13, 2007

TO: The Honorable Chairman and Board Members

THROUGH: R. Alan Shubert, P. E., C.B.O. – Development Services Director

FROM: Bill Stern, C.B.O., Chief Building Inspector

SUBJECT: 182 Coronado Road, El Paso, Texas 79907

The following is a brief chronology of the investigation of the referenced location:

1. First investigated on January 9, 2007. The building was found to be in an advanced state of disrepair, open and abandoned. The building has been used as a harborage by unwanted persons.
2. A certified condemnation letter was mailed to Jose Antonio Hernandez, 2645 Pikake Street, San Diego, CA 92154.
3. Certified notices of the public hearing scheduled for February 28, 2007 were mailed to the owners and all interested parties on February 16, 2007.
4. There has been some contact with the owner.
5. As of February 13, 2007, $1,704.63 are owed in property taxes.

The Department recommends that it be found:

1. That the main structure and accessory structure be condemned as substandard, and unfit for habitation or use and a hazard to the public health, safety, and welfare and
2. That the structure is not in substantial compliance with the municipal ordinances regulating fire protection, structural integrity, and disposal of refuse; and
3. That the structure's certificate of occupancy be revoked; and
4. That the structure cannot be repaired; and
5. That the main structure and accessory structure be demolished within 30 days; and
6. That the premises be cleaned of all weeds, trash, and debris within 30 days; and
7. That upon failure by the owner or any other interested party to comply with the order of the Building and Standards Commission the City may take whatever action is necessary to bring the property into compliance, and place a lien on the property for the work which will be done by the City.

JOHN COOK
MAYOR

JOYCE WILSON
CITY MANAGER

R. ALAN SHUBERT, PE, CBO
DEVELOPMENT SERVICES DEPARTMENT, DIRECTOR

CITY COUNCIL
ANN MORGAN LILLY, DISTRICT 1
SUSANNAH M. BYRD, DISTRICT 2
J. ALEXANDRO LOZANO, DISTRICT 3
MELINA CASTRO, DISTRICT 4
PRESI ORTEGA, JR., DISTRICT 5
EDDIE HOLGUIN JR., DISTRICT 6
STEVE ORTEGA, DISTRICT 7
BETO O'ROURKE, DISTRICT 8

DEVELOPMENT SERVICES DEPARTMENT

BUILDING STANDARDS ENFORCEMENT
January 17, 2007

Jose A. Hernandez
2645 Pikake Street
San Diego, CA 92154

Re: 182 Coronado Rd.
Blk: Coronado Place
Lot: N 50 FT of TR 11
Zoned: R4
COD07-01112
Certified Mail Receipt #
7105 8873 0193 6301 8178

To All Owners, Lienholders, and Mortgagees:

An inspection at the above referenced address has revealed that the structure is in violation of the El Paso Municipal Code, Chapter 18.50 International Property Maintenance Code, which states:

> **18.50.106.1 General.**
> When a structure or equipment is found by the Director to be unsafe, or when a structure is found unfit for human occupancy, or is found unlawful, such structure or equipment shall be condemned pursuant to the provisions of Chapter 2.38 of this code.

The El Paso Municipal Code Chapter 18.50 International Property Maintenance Code defines unsafe structure as follows:

> **18.50.106.1.1 Unsafe Structures.**
> An unsafe structure is one that is found to be dangerous to the life, health, property or safety of the public or the occupants of the structure by not providing minimum safeguards to protect or warn occupants in the event of fire, or because such structure contains unsafe equipment or is so damaged, decayed, dilapidated, structurally unsafe or of such faulty construction or unstable foundation, that partial or complete collapse is possible.
>
> **18.50.106.1.2 Unsafe Equipment**
> Unsafe equipment includes any boiler, heating equipment, elevator, moving stairway, electrical wiring or device, flammable liquid containers, or other equipment on the premises or within the structure that is in such disrepair or

condition that such equipment is a hazard to life, health, property or safety of the public or occupants of the premises or structure.

18.50.106.1.3 Structure Unfit for Human Occupancy.
A structure is unfit for human occupancy whenever the Director finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is unsanitary, vermin or rat infested, contains filth or contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public

The structure located at **182 Coronado Road** has the following violations:

a. The floors have not been maintained in a safe manner. [Sec. 305.4]

b. The walls have not been maintained in a safe manner free of holes and cracks. [Sec. 304.6]

c. The roof structure has not been maintained free of defects that may cause leaks. [Sec. 304.7]

d. The means of egress is/are inadequate and do not meet minimum code requirements. [Sec. 702.4]

e. The plumbing system is inadequate and does not meet minimum code requirements. [Sec. 504.1]

f. The electrical system is inadequate and does not meet minimum code requirements. [Sec. 604.3]

g. The HVAC system is inadequate and does not meet minimum code requirements. [Sec. 603.1]

h. The structure is open and accessible to unauthorized entry. [Sec. 301.3]

i. The premises are full of weeds, trash, and debris [Sec. 302.1 & Sec. 302.4].

j. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]

As a result of the aforementioned violations, the following action may be taken:

a. This case is being submitted to the City Building and Standards Commission for unsafe structures proceedings. The City Building and Standards Commission will decide if the structure is unsafe and if it should be vacated and secured, or demolished as per Chapter 2.38 of the El Paso Municipal Code.

182 Coronado Road

b. By authority of Chapter 18.02.103.9.3 of the El Paso Municipal Code the electrical service at this property may be disconnected at the request of the Building Permits and Inspections Department because of Electrical Code violations.

Many of these corrections will require a permit. Permits for commercial or rental property must be taken out by a bonded and insured contractor who is registered with the City of El Paso.

According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Housing Compliance Office of the Building Permits and Inspections, 5th floor, City Hall, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Should you have any questions regarding this matter, please contact me at 54l-4800.

FOR THE DIRECTOR FOR BUILDING PERMITS AND INSPECTIONS:

Zuleika Davila
Building Inspector

ZCD/nms

RECEIVED

JAN 25 2007

CITY OF EL PASO
DEVELOPMENT SERVICES
DEPARTMENT

1. Article Addressed to:

Jose A Hernandez
2645 Pikake Street
San Diego CA 92154
182 Coronado

COMPLETE THIS SECTION ON DELIVERY

A. Received by (Please Print Clearly) | B. Date of Delivery
ANTONIO HERNANDEZ 1-23-07

C. Signature
X [signature]
☐ Agent
☐ Addressee

D. Is delivery address different from item 1? ☐ Yes
If YES, enter delivery address below: ☐ No

3. Service Type
☒ Certified Mail

4. Restricted Delivery? (Extra Fee) ☐ Yes

2. Article Number (Copy from service label) 7105 8873 0193 6301 8178

PS Form 3811, July 1999 Domestic Return Receipt

NOTICE OF PUBLIC HEARING

To All Interested Parties:

You are hereby notified that at 5:30 p.m. on the **26th** day of **September, 2007** in the Council Chambers of City Hall, #2 Civic Center Plaza, El Paso, Texas, the Building and Standards Commission of El Paso (the "**Commission**") will hold a public hearing on the question of whether the buildings located on the property at **182 Coronado Road**, in El Paso, Texas, which property is more particularly described as:

LEGAL DESCRIPTION: The North 50 feet of Tract 11, CORONADO PLACE SUBDIVISION, a subdivision in El Paso County, Texas according to the plat thereof, recorded in Volume 7, Page 56, Plat Records of El Paso County, Texas

is unsafe and dangerous.

According to the real property records of the County of El Paso, Texas, **Jose Antonio Hernandez** (the "**Owner**"), **2645 Pikake Street, San Diego, CA 92154,** is listed as the owner of the real property described herein.

According to the real property records of El Paso County, you own or have an interest in the real property described in this notice. If you no longer own or have an interest in the property, you must execute an affidavit stating that you no longer own or have an interest in the property and stating the name and last known address of the person who acquired the property or interest from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Building Standards Enforcement Division of the Building Permits and Inspections, 5th floor, City Hall, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice.

The Owner of said property is hereby ordered to appear before the Building and Standards Commission and any mortgagees, lien holders, and other persons having an interest in said property are entitled to appear before the Commission at said date, hour, and place to show cause why said buildings should not be declared a nuisance and ordered to be abated. The Owner, lien holders, mortgagees, or any other person having an interest in the property are hereby required to submit at the hearing proof of the scope of any work that may be required to bring the building into compliance with Title 18, as mandated by Section 18.50 of the Municipal Code, and to specify the time it will take to reasonably perform the work.

At the hearing, the Owner, lien holders, mortgagees, or any other person having an interest in the property must present to the Commission any evidence showing that the structures or part thereof is safe.

All documents such as building plans, specifications, drawings, reports from design professionals and any other required documents must be presented to the Commission at this hearing.

The time periods, which govern the completion of work ordered by the commission, are outlined in Chapter 2, Subsection 2.38.080 of the Municipal Code of the City of El Paso, and pursuant to State law.

If the Owner fails, neglect or refuse to comply with the order of the Commission the City may pursue one, or more of the following actions:

I) the city will perform any and all work needed to bring the property into compliance with this order, at its own expense, but for and on account of the Owners, of said property, the cost of which shall be assessed as a lien against the property and;

II) assess a civil penalty against the property Owners for failure to repair, remove or demolish said building in an amount not to exceed $1,000.00 a day for each violation, or $10.00 a day if the Owners show that the property is the Owner's lawful homestead; and

III) appoint a receiver as permitted by state law; and

IV) any other remedies permitted by state law.

Any civil penalty or assessment imposed will accrue interest at a rate of ten (10) percent a year from the date of the assessment until paid in full;

The City Clerk is ordered to provide notice of this hearing to the record Owners and all other persons having an interest in the property as provided by law.

APPROVED AS TO FORM:

_____
Ernesto Rodriguez
Assistant City Attorney

APPROVED AS TO CONTENT:

_____
Bill Stern, C.B.O.
Chief Building Inspector
Building Permits and Inspections Department

I, RICHARDA DUFFY MOMSEN, City Clerk of the City of El Paso, hereby certify that a true and correct copy of the foregoing Notice regarding the property located at **182 Coronado Road** was PUBLISHED in the official City newspaper on the ____day of_____, 2007.

Richarda Duffy Momsen

I certify that a true and correct copy of the foregoing Notice regarding the property at **182 Coronado Road**, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Jose Antonio Hernandez
2645 Pikake Street
San Diego, CA 92154

Date:
Time:

Inspector

I certify that a true and correct copy of the foregoing Notice regarding the property at **182 Coronado Road**, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Jose Antonio Hermandez
182 Coronado Road
EL Paso, Texas 79915

Date:
Time:

Inspector

I certify that a true and correct copy of the foregoing Notice regarding the property at **182 Coronado Road**, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Jaime Gallegos
9300 McCabe
El Paso, Texas 79925

Date:
Time:

Inspector

I certify that a true and correct copy of the foregoing Notice regarding the property at **182 Coronado Road**, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Maria Luisa Gomez
10529 Valle Blanco Dr.
El Paso, Texas 79927

Date:
Time:

Inspector

I certify that a true and correct copy of the foregoing Notice regarding the property at **182 Coronado Road**, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Alejandra Velasquez
7507 Benson
El Paso, Texas 79915

Date:
Time:

Inspector

I certify that a true and correct copy of the foregoing Notice regarding the property at **182 Coronado Road**, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Javier Gallegos
10529 Valle Blanco Dr.
El Paso, Texas 79927

Date:
Time:

Inspector

I certify that a true and correct copy of the foregoing Notice regarding the property at **182 Coronado Road** , was HAND-DELIVERED to:

City of El Paso
C/O City Clerk
#2 Civic Center Plaza
El Paso, TX 79901

Date:
Time:

Inspector

I certify that a true and correct copy of the foregoing Notice regarding the property at **182 Coronado Road**, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Governor of the Ysleta Del Sur Pueblo Indian Tribe
AKA Tigua Indian Community
119 S. Old Pueblo Road
El Paso, Texas 79907

Date:
Time:

Inspector

I certify that a true and correct copy of the foregoing Notice regarding the property at **182 Coronado Road,** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso Central Appraisal District
5801 Trowbridge Ave.
El Paso, Texas 79925

Date:
Time:

Inspector

I certify that a true and correct copy of the foregoing Notice regarding the property at **182 Coronado Road,** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso County Probate Court
500 E. San Antonio Avenue, Suite 703
El Paso, Texas 79901

Date:
Time:

Inspector

I certify that a true and correct copy of the foregoing Notice was POSTED at **182 Coronado Road**, El Paso, Texas.

Date:
Time:

Inspector

UNSAFE STRUCTURES REPORT

BUILDING PERMITS AND INSPECTIONS

DATE OF EXAMINATION: February 13, 2007 **REP. DISTRICT:** 6

ADDRESS: 182 Coronado Road **ZONED:** R-4

LEGAL DESCRIPTION: The North 50 feet of Tract 11, CORONADO PLACE SUBDIVISION, a subdivision in El Paso County, Texas, according to the plat thereof, recorded in Volume 7, Page 56 Plat Records of El Paso County, Texas

OWNER: Jose A. Hernandez **ADDRESS:** 2645 Pikake Street, San Diego, CA 92154

BUILDING USE: Triplex

TYPE OF CONSTRUCTION: V

FOOTINGS: Concrete
CONDITION: Unable to determine condition of footing due to subterranean placement. A structural engineer should be hired to evaluate actual condition.

FOUNDATION WALL: None
CONDITION: N/A

FLOOR STRUCTURE: Concrete. Slab on grade
CONDITION: Cracks noted. A structural engineer should be hired to evaluate actual conditions.

EXTERIOR WALLS: Wood frame with drywall and plaster, CMU

HEIGHT: 10' **THICKNESS:** 6-8"

CONDITION: Poor. Cracks noted throughout. Signs of wall failure noted. A structural engineer should be hired to evaluate the actual condition.

INTERIOR WALLS & CEILINGS: Wood framing with sheetrock, plaster.
CONDITION: Poor. A registered contractor should be hired to evaluate the actual condition.

ROOF STRUCTURE: Wood frame with built up roofing.
CONDITION: Poor. Due to lack of maintenance and exposure to the elements, a portion of the roof has collapsed. A registered roof or building contractor must be hired to evaluate roofing system.

DOORS, WINDOWS, ETC.: Wood frame and aluminum frame doors and windows.
CONDITION: Poor. Most doors and windows are broken and nonfunctional. Will need replacement.

MEANS OF EGRESS:
CONDITION: Does not meet code.

PLUMBING: Poor. A licensed plumbing contractor must be hired to evaluate plumbing system and submit a report to this department on the corrective action required to bring the system up to minimum code compliance.

ELECTRICAL: Poor. A licensed electrical contractor must be hired to evaluate the electrical system and submit a report to this department on the corrective action required to bring the system up to minimum code compliance.

MECHANICAL: Poor. A licensed mechanical contractor must be hired to evaluate the entire mechanical system and submit a report to this department on the corrective action required to bring the system up to minimum code.

IF CONDEMNED, HOW MANY PERSONS WILL BE AFFECTED: None

WARNING POSTED: Yes **BARRICADED:** No **POLICE AID REQD.:** Yes

REMARKS: This is an open and abandoned triplex unit. The buildings were found to be in an advanced state of disrepair. This department recommends that the main structure and accessory structure be demolished within 30 days and premises be cleaned of all trash and weeds within 30 days.

Zuleika Davila
Building Inspector

EL PASO CITY-COUNTY HEALTH &ENVIRONMENTAL DISTRICT
ENVIRONMENTAL HEALTH

MEMORANDUM

DATE: 01-25-07

MEMO TO: William Stern C.B.O., Residential Inspector Supervisor

FROM: Ben Blumenfled, Environmental Health Inspector

SUBJECT: Condemnation Report

RE: Address: 182 Coronado

An inspection of the property was conducted at 182 Coronado and the conditions checked were found in violation of Title 9 of the El Paso Municipal Code.

SECTION 9.04 - SOLID WASTE STORAGE AREA
Trash noted through out the yard.

SECTION 9.04.340 – ACCUMULATIONS
Broken glass, tires, rubbish and debris noted.

SECTION 9.16 - NUISANCE
Waste oil was found the property.

SECTION 9.16.010 – DESIGNATED
The structure was noted to be unsecured, the font door is missing and many broken windows we noted in which access could be gained to enter the structure. Heavy damage to the structure w noted inside and out.

SECTION 9.28 -RAT CONTROL
Rodent droppings were noted.

If you require additional information or assistance, please feel free to call at Tel. (915) 594-1568 or Fax: at 594-9655

Account Status

Prev Account | Next Account | Prev. Owner | Next Owner | Acct History | Notes | Go To:

HORT
ACTB006 v1.160

02/13/2007 11:01:19
ACTEP

STATUS DETAIL | Expand Fees | Summary

Account Information

Account No: C835-999-0010-5900 Owner No: 0
Certified Owner: HERNANDEZ, JOSE A
Parcel Address: 182 CORONADO
Amount Due as of: 02/13/2007 Roll Code: REAL PROPERTY

Tax Units

Tax Unit Description:
List of Tax Units: 1 5 6 7 8
AG INCLUDED | Remove Fees | Countywide

Tax Unit,Yr, Rec. Type

Tax Unit:
Year:
Rec. Type:
Multi Select

Amount Due/Paid Information

Year	Gross Value	H	O	V	D		Base Levy	Paid Levy	Write Off	Remaining Levy	Fees	Refund	Amount Due
2006	$70,833	Y				Exemption	$1,593.01	$.00	$.00	$1,593.01	$111.52	$.00	$1,704.53
2005	$71,667	Y				Exemption	$1,751.66	$1,751.66	$.00	$.00	$262.75	$.00	$.00
2004	$68,048	Y					$1,660.02	$1,660.02	$.00	$.00	$116.20	$.00	$.00
2003	$62,703	Y					$1,443.45	$1,443.45	$.00	$.00	$842.87	$.00	$.00
2002	$62,703	Y					$1,425.92	$1,425.92	$.00	$.00	$213.88	$.00	$.00
2001	$62,703	Y					$1,401.02	$1,401.02	$.00	$.00	$.00	$.00	$.00
2000	$61,130	Y					$1,323.15	$1,323.15	$.00	$.00	$92.64	$.00	$.00
1999	$61,130	Y					$1,313.32	$1,313.32	$.00	$.00	$118.19	$.00	$.00
1998	$61,130	Y					$1,339.94	$1,339.94	$.00	$.00	$93.79	$.00	$.00
						Totals	$14,495.24	$12,902.23	$.00	$1,593.01	$1,963.77	$.00	$1,704.53

Last Payment Date:
Last Payer:
Alert