

3001 RIVERA



**BUILDING AND STANDARDS BOARD AGENDA ITEM #5 FOR
WEDNESDAY, OCTOBER 29, 2014**

**CITY DEVELOPMENT DEPARTMENT
BUILDING SAFETY DIVISION**

MEMORANDUM
October 14, 2014

TO: The Honorable Chairman and Board Members

THROUGH: Victor Morrison-Vega, Deputy Director, City Development Department

FROM: Ron Roth, C.B.O., Deputy Building Official

SUBJECT: 3001 Rivera Ave., El Paso, Texas, 79901

The following is a brief chronology of the investigation of the referenced location:

- 1) First investigated on or about July 11, 2014. The commercial structure was built on or about 1950 of cultured masonry block and wood framing. The structure was found open, abandoned, vandalized and being used as harborage by unwanted persons. The structure is located right across from Beall Elementary School. The roof and ceiling system is failing and collapsing. The interior walls are exposing the wood framing members due to vandalism. The electrical, mechanical and plumbing systems are nonexistent. The property is full of trash and debris.
- 2) A certified condemnation letter was mailed to National Realty Acceptance Co. LLC.
- 3) Certified notices of the public hearing scheduled for October 29, 2014, were mailed to the owners and all interested parties on October 8, 2014.
- 4) As of October 13, 2014, \$19,598.33 in taxes is owed.

The owner has been notified of the property violations at this property. To date there has been no response or corrective action taken, and therefore the Department recommends that it be found:

- 1) That the structure be condemned as substandard, and unfit for habitation or use and a hazard to the public health, safety, and welfare; and
- 2) That the structure is not in substantial compliance with the municipal ordinances regulating fire protection, structural integrity, and disposal of refuse; and
- 3) That the structure's certificate of occupancy be revoked; and
- 4) That the structure can be rehabilitated; and
- 5) That a structural evaluation by an engineer be submitted for rehabilitation
- 6) That the structure be secured within thirty (30) days and maintained secure thereafter; and
- 7) That the property be registered as a Vacant building with the City of El Paso within thirty (30) days; and
- 8) That the premises be cleaned of all weeds, trash, and debris within thirty (30) days and maintained clean thereafter; and
- 9) That upon failure by the owner or any other interested party to comply with the order of the Building and Standards Commission the City may take whatever action is necessary to bring the property into compliance, and place a lien on the property for the work which will be done by the City.

Building Safety Division
September 10, 2014
NOTICE OF VIOLATION

National Realty Acceptance Co LLC
PO Box 4010
East Lansing, MI 48826-4010

Re: 3001 Rivera Ave
Blk: 2 East El Paso
Lot: 1 to 3 & W5.33 ft of 4 (11246 Sq Ft)
Zoned: A-3
ENHS14-01256
91 7199 9991 7030 7809 1405

To All Owners, Lienholders, and Mortgagees:

An inspection at the above referenced address has revealed that the structure is in violation of the El Paso Municipal Code, Chapter 18.50, Property Maintenance Code, which states:

18.50.108.1 General.

When a structure or equipment is found by the Director to be unsafe, or when a structure is found unfit for human occupancy, or is found unlawful, such structure or equipment shall be condemned pursuant to the provisions of Title 2.38 of the Municipal Code.

The El Paso Municipal Code Chapter 18.50 International Property Maintenance Code defines unsafe structure as follows:

18.50.108.1.1 Unsafe Structures.

An unsafe structure is one that is found to be dangerous to the life, health, property or safety of the public or the occupants of the structure by not providing minimum safeguards to protect or warn occupants in the event of fire, or because such structure contains unsafe equipment or is so damaged, decayed, dilapidated, structurally unsafe or of such faulty construction or unstable foundation, that partial or complete collapse is possible.

18.50.108.1.2 Unsafe Equipment

Unsafe equipment includes any boiler, heating equipment, elevator, moving stairway, electrical wiring or device, flammable liquid containers, or other equipment on the premises or within the structure that is in such disrepair or condition that such equipment is a hazard to life, health, property or safety of the public or occupants of the premises or structure.

18.50.108.1.3 Structure Unfit for Human Occupancy.

A structure is unfit for human occupancy whenever the Director finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is unsanitary, vermin or rat infested, contains filth or contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public

The structure located at **3001 Rivera Ave., El Paso, TX** is in violation of the requirements found in the following sections of the 2009 International Property Maintenance Code as adopted in the El Paso City Code, Chapter 18.50, Property Maintenance Code:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and

- walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]
- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]
 - c. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 305.1, 305.2, 305.3, 305.4, 305.5, 305.6]
 - d. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
 - e. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
 - f. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
 - g. The building must comply with the minimum criteria and conditions for light. [Sec.402.1, 402.2, 402.3]
 - h. The building must comply with the minimum criteria and conditions for ventilation. [Sec.403.1, 403.2, 403.3, 403.4, 403.5]
 - i. The building must comply with the minimum criteria of the provisions for required facilities. [Sec. 502.1, 502.2, 502.3, 502.4,502.4.1, 502.5]
 - j. The building must comply with the minimum criteria of the provisions for toilet rooms. [Sec. 503.1, 503.2, 503.3, 503.4]
 - k. The building must comply with the minimum criteria of the provisions for plumbing systems and fixtures. [Sec. 504.1, 504.2, 504.3]
 - l. The building must comply with the minimum criteria of the provisions for heating facilities. [Sec. 602.2, 602.3, 602.4, 602.5]
 - m. The building must comply with the minimum criteria of the provisions for electrical facilities. [Sec. 604.1,604.2, 604.3, 604.3.1, 604.3.1.1, 604.3.2, 604.3.2.1]
 - n. All electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner. [Sec. 605.1, 605.2, 605.3]
 - o. Means of egress & Emergency escape opening - A safe, continuous and unobstructed path of travel has not been provided from all points in the building or structure to the public way. [Sec. 702.1, 702.2, 702.3, 702.4]
 - p. The required fire-resistance rating of fire-resistance-rated walls, fire stops, shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2]
 - q. All systems, devices and equipment to detect a fire, actuate an alarm, or suppress or control a fire or any combination thereof shall be maintained in an operable condition at all times. [Sec. 704.1, 704.1.1, 704.2, 704.3, 704.4]

- r. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]
- s. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within 30 days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the City Development Department, Building Safety Division.

As a result of the aforementioned violations, the following action may be taken:

- a. This case is being submitted to the City Building and Standards Commission for unsafe structures proceedings. The Building and Standards Commission will decide if the structure is unsafe and if it should be vacated and secured, or demolished as per Title 2.38 of the El Paso Municipal Code.
- b. By authority of Chapter 18.02.103.10.3.3 of the El Paso Municipal Code the electrical service at this property may be disconnected at the request of the City Development Department, Building Safety Division because of Electrical Code violations.

Many of these corrections will require a permit. Permits for commercial or rental property must be taken out by a bonded and insured contractor who is registered with the City of El Paso.

According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Building Safety Division office, 801 Texas Ave., El Paso, Texas, 79901, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Should you have any questions regarding this matter, please contact me at (915) 212-1815.

Nellie Avalos
Building Inspector

NOTICE OF PUBLIC HEARING

To all interested parties:

The owners, mortgagee, lien holders and any others with a legal interest in the property described below are hereby ordered to appear before the Building and Standards Commission, herein after referred to as the “Commission”, at the following time and place:

LOCATION: El Paso City Hall, City Council Chamber, 300 N. Campbell, 1st Floor, El Paso, Texas 79901

DATE: October 29, 2014

TIME: 5:30 p.m.

PROPERTY: 3001 Rivera Ave., El Paso, Texas, also described as Parcel 1: All of Lot 1 and the West 15 feet, 7 inches of Lot 2, Block 2, SUPPLEMENTAL MAP NO. 1 OF EAST EL PASO, an addition to the City of El Paso, El Paso, County, Texas, according to the plat thereof, recorded in Volume 1, Page 51, Plat Records of El Paso County, Texas. PARCEL 2: All of Lot 3 and the East 9.4167 feet of Lot 2 and the West 5.333 feet of Lot 4, Block 2, SUPPLEMENTAL MAP NO. 1 OF EAST EL PASO, an addition to the City of EL Paso, El Paso County, Texas, according to the plat thereof, recorded in Volume 1, Page 51, Plat Records of El Paso County, Texas.

The property has been determined to be substandard based upon violations of the minimum standards of the 2009 Building Codes, adopted and incorporated in the El Paso City Code, Chapter 18, more specifically addressed below.

According to the real property records of El Paso County, and other relevant public records, National Realty Acceptance Co LLC, P. O. Box 4010, East Lansing, MI, 48826-4010, is the owner(s), herein after referred to as the “Owners” of the property. If you no longer own or have an interest in the property, you must execute an affidavit stating that you no longer own or have an interest in the property and stating the name and last known address of the person who acquired the property from you, if applicable. The affidavit must be delivered in person or by certified mail, return receipt requested, to The Building and Safety Division of the City Development Department, 801 Texas, El Paso, Texas 79901, no later than the 20th day after the date you receive this notice. If you do not execute and deliver the affidavit, it will be presumed that you own or have an interest in the property, even if you do not.

On or about July 11, 2014, an inspection of the property was conducted by the Building Safety Division and the following violations were identified:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]

- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]
- c. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 305.1, 305.2, 305.3, 305.4, 305.5, 305.6]
- d. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- e. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- f. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
- g. The building must comply with the minimum criteria and conditions for light. [Sec.402.1, 402.2, 402.3]
- h. The building must comply with the minimum criteria and conditions for ventilation. [Sec.403.1, 403.2, 403.3, 403.4, 403.5]
- i. The building must comply with the minimum criteria of the provisions for required facilities. [Sec. 502.1, 502.2, 502.3, 502.4,502.4.1, 502.5]
- j. The building must comply with the minimum criteria of the provisions for toilet rooms. [Sec. 503.1, 503.2, 503.3, 503.4]
- k. The building must comply with the minimum criteria of the provisions for plumbing systems and fixtures. [Sec. 504.1, 504.2, 504.3]
- l. The building must comply with the minimum criteria of the provisions for heating facilities. [Sec. 602.2, 602.3, 602.4, 602.5]
- m. The building must comply with the minimum criteria of the provisions for electrical facilities. [Sec. 604.1,604.2, 604.3, 604.3.1, 604.3.1.1, 604.3.2, 604.3.2.1]
- n. All electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner. [Sec. 605.1, 605.2, 605.3]

- o. Duct systems shall be maintained free of obstructions and shall be capable of performing the required function. [Sec. 607.1]
- p. Means of egress & Emergency escape opening - A safe, continuous and unobstructed path of travel has not been provided from all points in the building or structure to the public way. [Sec. 702.1, 702.2, 702.3, 702.4]
- q. The required fire-resistance rating of fire-resistance-rated walls, fire stops, shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2]
- r. All systems, devices and equipment to detect a fire, actuate an alarm, or suppress or control a fire or any combination thereof shall be maintained in an operable condition at all times. [Sec. 704.1, 704.1.1, 704.2, 704.3, 704.4]
- s. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]

The owners are entitled to show cause that the property is safe, does not constitute a dangerous structure and should not be declared a nuisance and ordered abated by presenting relevant evidence and testimony. If the owners advocates for repair, then they bear the burden of proof to demonstrate the scope of any work that may be required to bring the property into compliance with Chapter 18.50 and the time it will take to reasonably perform the work. The allowable time periods for repair are governed by Texas Local Government Code, Sections 214.001(h), (i), (j) and (k). Any document relied upon to demonstrate that the property is safe or that it can be repaired must be presented to the Commission at the hearing, including building plans, specifications, drawings, or reports from professionals and any other relevant documentation.

If the owners fail to comply with the order of the Commission, the City may pursue one or more of the following actions:

Perform any and all work necessary to bring the property into compliance with the Commission's order;

Assess civil penalties, provided for in the Commission's order, in an amount not to exceed \$1,000 per day or \$10 per day if the Property has a homestead exemption, that will accrue interest of 10% per year until paid in full;

Appoint a receiver as permitted by state law; and

Any other remedies permitted by state law.

Commission orders may be appealed to the State District Court within 30 days of the Final order.

The Commission's authority and procedures in regard to a Dangerous Structure Hearing may be found in Chapter 2.38 of the El Paso City Code and in their duly adopted bylaws. A copy of the ordinance adopting the most current version of Chapter 2.38 is enclosed. The bylaws may be

obtained at the Building Safety Division of the City Development Department, 801 Texas, El Paso, Texas 79901 or by calling (915) 212-1517.

This notice will be recorded in the real property records of El Paso County and will be binding on subsequent grantees, lien holders or other transferees of an interest in the Property.

The City Clerk is ordered to provide notice of this hearing to the record owners and all other interested parties, required by law, who are listed following this notice, and file this notice in the real property records of El Paso County.

FAILURE OF THE OWNER AND/OR LIENHOLDER OR MORTGAGEE TO TAKE THE ORDERED ACTION MAY RESULT IN THE CITY TAKING THE ORDERED ACTION AND FILING A LIEN AGAINST THE PROPERTY.

The City of El Paso appreciates your cooperation and prompt attention to remedying the nuisances on the property. Please do not hesitate to contact me should you have any additional questions, comments or concerns relative to this notice.

APPROVED AS TO FORM

APPROVED AS TO CONTENT

Wendi N Vineyard
Assistant City Attorney

Ron Roth, C.B.O.
Deputy Building Official

I, RICHARDA DUFFY MOMSEN, City Clerk of the City of El Paso, hereby certify that a true and correct copy of the foregoing Notice regarding the property located at 3001 Rivera Ave., El Paso, Texas was PUBLISHED in the official City newspaper on the ___ day of _____, 2014.

Richarda Duffy Momsen

I certify that a true and correct copy of the foregoing Notice regarding the property at 3001 Rivera Ave., El Paso, Texas 79907, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

National Realty Acceptance Co. LLC
P. O. Box 4010
East Lansing, MI 48826-4010

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 3001 Rivera Ave., El Paso, Texas 79907, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Raymond Malphurs/Russell A. Malphers, as Trustee
10300 Woodruff Ct.
El Paso, Texas 79925-6355

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 3001 Rivera Ave., El Paso, Texas 79907, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Alejandro Lopez and heirs
3001 Rivera Ave.
El Paso, Texas 79905

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 3001 Rivera Ave., El Paso, Texas 79907, was HAND-DELIVERED to:

City of El Paso
C/O City Clerk
300 N. Campbell
El Paso, Texas 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 3001 Rivera Ave., El Paso, Texas 79907, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Governor of the Ysleta Del Sur Pueblo Indian Tribe
AKA Tigua Indian Community
119 S. Old Pueblo Road
El Paso, Texas 79907

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 3001 Rivera Ave., El Paso, Texas 79907, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso Central Appraisal District
5801 Trowbridge Ave.
El Paso, Texas 79925

Date: _____
Time: _____
Inspector: _____



UNSAFE STRUCTURES REPORT

BUILDING SAFETY DIVISION

DATE OF EXAMINATION: September 14, 2014

REP. DISTRICT: 8

ADDRESS: 3001 Rivera Avenue

ZONED: A-3

LEGAL DESCRIPTION: Parcel 1: All of Lot 1 and the West 15 feet, 7 inches of Lot 2, SUPPLEMENTAL MAP NO.1 OF EAST EL PASO, an addition to the City of El Paso, El Paso County, Texas, according to the plat thereof, recorded in Volume 1, Page 51, Plat Records of El Paso County, Texas.

Parcel 2: All of Lot 3 and the East 9.4167 feet of Lot 2 and the West 5.333 feet of Lot 4, Block 2, SUPPLEMENTAL MAP NO. 1 OF EAST EL PASO, an addition to the City of El Paso, El Paso County, Texas, according to the plat thereof, recorded in Volume 1, Page 51, Plat Records of El Paso County, Texas.

OWNER: National Realty Acceptance Co., LC **ADDRESS:** PO Box 4010
East Lansing, MI 48826-4010

BUILDING USE: Abandoned commercial building w/multifamily dwellings

TYPE OF CONSTRUCTION: V, Wood frame, brick veneer and CMU

FOOTINGS: Unable to determine condition of footing due to subterranean placement.

CONDITION: Unknown. A structural engineer should be hired to evaluate actual condition.

FOUNDATION WALL: N/A

CONDITION: N/A

FLOOR STRUCTURE: Wood with wood frame covered with carpet and full of debris accumulation.

CONDITION: Poor. Several areas of the floor system are extremely soft and uneven. A structural engineer or registered contractor must be hired to evaluate the flooring system.

EXTERIOR WALLS: Brick and CMU

HEIGHT: 10' – 12' +/-

THICKNESS: 8" - 10" +/-

CONDITION: Fair. Due to lack of maintenance and exposure to the elements, some brick pointing and repairs are recommended. A structural engineer should be hired to evaluate structural elements of the building and submit a report on the corrections required to make the building safe.

INTERIOR WALLS & CEILINGS: CMU, wood frame & gypsum board w/plaster

CONDITION: Poor. Most of the interior has been vandalized; the gypsum board has been removed from the walls exposing the damaged wood framing members and CMU.

ROOF STRUCTURE: Built up pitch roof, wood framing with composite shingle roof covering.

CONDITION: Poor. Several areas of the roof are caving in due to lack of maintenance. A registered roofing contractor or building contractor must be hired to evaluate the roofing system and submit a report of required corrections to bring the roof system into code compliance.

DOORS, WINDOWS, ETC.: Wood doors and wood frame windows, some w/wrought iron guards.

CONDITION: Bad. Will need to repair or replace all doors and windows, so they are operational and meet egress requirements.

MEANS OF EGRESS: Does not meet code requirements.

CONDITION: Poor. Doors & windows need replacing or repairs to make them operational.

PLUMBING: A licensed plumber should be hired to bring system up to code.

ELECTRICAL: A licensed electrician should be hired to bring system up to code.

MECHANICAL: A licensed mechanical contractor should be hired to bring system up to code.

IF CONDEMNED, HOW MANY PERSONS WILL BE AFFECTED: None

WARNING POSTED: Yes

BARRICADED: No

POLICE AID REQD.: No

REMARKS: Upon inspection of this commercial structure built on or about 1950, it was found in a state of disrepair, abandoned and open to harborage by unwanted persons. The interior walls are showing signs of advanced deterioration, vandalism and harborage to unwanted persons. The structure should be secured within thirty days and maintained secure thereafter. The property should be cleaned of all weeds, trash and debris within thirty days and maintained clean thereafter.

Nellie Avalos

Building Inspector

TAX REPORT

Appraisal & Collection Technologies - EL PASO

Action Edit Query Record Field Help Entitlements Accounts Statements Window

ORACLE

Account Status

Prev. Acc... Next Acc... Prev. Owner Next Owner Acct History Acct Summary **Notes** Documents Go To:

EVAR
ACT8006 v1.255 **ACCOUNT NO(E01499900200100): Bankruptcy 09-31431 has been closed** 10/13/2014 12:46 ACTEP

STATUS DETAIL Expand Fees Summary

Account Information

Account No. **E014-999-0020-0100** Roll Code REAL PROPERTY

Certified Owner NATIONAL REALTY ACCEPTANCE CO LLC

Parcel Address 3001 RIVERA AVE

Amount Due as of 10/13/2014 CAD No. 392925

Tax Units

Tax Unit Description

List of Tax Units 1 3 6 7 8 9009 9089

AG INCLUDED Remove Fees Countywide Multi Select

Tax Unit, Yr, Rec. Type

Tax Unit
Year
Rec. Type

Amount Due/Paid Information

Year	Gross Value	H	O	V	D	Base Levy	Paid Levy	Write-Off	Remaining Levy	Fees	Refund	Amount Due
2014	\$295,886					\$8,096.28	\$0.00	\$0.00	\$8,096.28	\$0.00	\$0.00	\$8,096.28
2013	\$290,883					\$7,810.96	\$0.00	\$0.00	\$7,810.96	\$3,492.83	\$0.00	\$11,303.79
2012	\$282,605					\$7,372.38	\$7,372.38	\$0.00	\$0.00	\$2,208.03	\$0.00	\$0.00
2011	\$267,409					\$7,317.10	\$7,202.80	\$0.00	\$114.30	\$83.96	\$0.00	\$198.26
2010	\$258,226					\$6,562.95	\$6,562.95	\$0.00	\$0.00	\$984.43	\$0.00	\$0.00
2009	\$232,606					\$5,794.99	\$5,794.99	\$0.00	\$0.00	\$3,148.74	\$0.00	\$0.00
2008	\$224,662					\$5,780.82	\$5,780.82	\$0.00	\$0.00	\$1,681.33	\$0.00	\$0.00
2007	\$201,918					\$5,086.54	\$5,086.54	\$0.00	\$0.00	\$2,508.35	\$0.00	\$0.00
2006	\$201,918					\$5,843.95	\$5,843.95	\$0.00	\$0.00	\$833.40	\$0.00	\$0.00
Totals						\$106,617.32	\$90,595.78	\$0.00	\$16,021.54	\$14,941.07	\$0.00	\$19,598.33

Last Payment Date
Last Payer

Alert

11:46 AM
10/13/2014